

National Inspection Services

Report: 280116 11/14/2024

VIN: 1XPBDP9X4LD669390

Commercial Credit Group, Inc (Mark Wenzel) 525 N Tryon Street, Charlotte, NC 28202 USA (704) 414-2456

2020 PETERBILT 579

	SPECIFICATIONS
ENGINE	PACCAR MX13 12.9L 455 HP
ENG BRAKE	YES
ENG SERIAL	Y210884
FUEL / TANKS	DIESEL - 2 ALUM
EXHAUST	SINGLE
EXTERNAL BREATHERS	SINGLE
TRANSMISSION	AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
WET LINE	YES
AXLE TYPE	TANDEM - F 12,000 LB / R 19,000 LB
GVWR	50,000
FRAME	SINGLE
SUSPENSION	AIR RIDE
TIRE SIZE	295/75/22.5
WHEELS	F ALUMINUM / R ALUMINUM
WHEEL 5TH	MANUAL
AIR COND	YES, NOT OPERATIONAL
AUX POWER UNIT?	YES, NOT OPERATIONAL
DUAL BUNK	YES
INTERIOR COLOR	TAN
RADIO	AM/FM / BLUE, NOT OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	AIR RIDE
EXTERIOR COLOR	GREEN
BUMPER	CHROME
EXTERIOR OPTS	HEATED MIRRORS, FULL FAIRINGS
COLLISION AVOIDANCE?	YES




BRAKES		
LEFT FRONT	RIGHT FRONT	
15	15	
LEFT REAR 1	RIGHT REAR 1	
19	19	
LEFT REAR 2	RIGHT REAR 2	
18	19	


TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
18 / 32 MICHELIN ALUMINUM		13 / 32 MICHELIN ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
8 / 32 ROADMASTER ALUMINUM	4/32 ROADMASTER ALUMINUM	13 / 32 ROADMASTER ALUMINUM	5/32 ROADMASTER ALUMINUM
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
14 / 32 MICHELIN ALUMINUM	14 / 32 BRIDGESTONE ALUMINUM	11/32 BRIDGESTONE ALUMINUM	15 / 32 MICHELIN ALUMINUM
FRONT TIRE	S : 295/75/22.5	REAR TIRES	3 : 295/75/22.5

		GENERAL OBSERVATIONS
OIL MILKY?	NA	LIGHTS WOR
OIL LEAKS?	YES	WIPERS WOR
WATER LEAKS?	NO	GAUGES WO
OIL IN COOLANT?	NO	AIR HORN WO
CLUTCH PLAY?	NA	CITY HORN V
STARTS?	NO	
DRIVES	NO	

LIGHTS WORK?	NA
WIPERS WORK?	NA
GAUGES WORK?	NA
AIR HORN WORKS?	NA
CITY HORN WORKS?	NA

WEAR & TEAR DETAIL		
DIAGNOSTICS	NO POWER COULD NOT RUN OR CHECK ALL FUNCTIONS	
TIRES	3 TIRES UNDER 10/32	
STEERING WHEEL	SURFACES HAVE WEAR. EMBLEM MISSING FROM THE CENTER	
FELIDED	DIG SENDED CODADED DELINID LISADI IGUIT	





Condition report only. National Inspection Services does not guarantee mechanical reliability.